

**B. M. ROSS AND ASSOCIATES LIMITED**

**Engineers and Planners**

62 North Street, Goderich, ON N7A 2T4

p. (519) 524-2641 [www.bmross.net](http://www.bmross.net)

**VIA EMAIL ONLY**

File No. 00221

October 7, 2024

Scott McLeod, Works Manager  
Municipality of Arran-Elderslie  
1925 Bruce Road 10, Box 70  
Chesley, ON N0G 1L0

**Re: Pearce Bridge, Structure E12**

We completed an inspection of the above structure on May 31, 2024 and due to the condition of various bridge components we recommended the bridge be closed until the structure is repaired or replaced. However, based on specifics pertaining to this bridge we do not think it would be cost effective over the long term to rehabilitate this structure. A summary of our observations and reasons for our recommendations follow.

The existing bridge is a steel truss bridge bearing on tall concrete abutments installed to accommodate for high water levels and the elevated roadway approaches. It is anticipated that this bridge was originally constructed in 1930. According to our records, this structure underwent repairs in 1971, 2002 and 2008. It was recommended in 2002 that future expenditures on this bridge be put towards replacing this structure. We agree with that recommendation given that the existing bridge is now over 90 years old, truss members are buckling which reduces their load carrying capacity, the poor alignment of the bridge relative to the road, the fact the structure is a single lane bridge with a load limit, the abutment shifted in the past and may do so again in the future, and the fact that when we re-analyzed the load limit of the aging truss members the load carrying capacity of the bridge may have to be reduced further. If the load limit is reduced from 8 to 5 tonnes it is not practical for passing snow removal equipment over it.

Enclosed with this letter is a copy of the OSIM report that includes photos to illustrate the deficiencies identified during our review. When reviewing the structure the following deficiencies were identified.

- Abutments have shifted in the past and there is a large crack in the south abutment. Efflorescence staining over 5% of the surface and should be removed and replaced.
- Top flange of most of the cross beams are corroding and some have lost 50% of their cross-sectional area.

- About 25 to 30% of the floor beams (stringers) are deteriorated to the point that the beams are not providing any support for the bridge deck. Many of the other beams are still providing some support but are also in poor condition.
- The wooden deck is still in fair condition, but allows water to pass through the deck and on to the floor beams that are corroding and the deck will have to be removed and replaced to complete all the repairs.
- The bridge trusses on each side of the bridge are buckling. The buckle along the bottom tension chords is very obvious, and the top of the trusses are also bent. This condition reduces the ultimate capacity of the trusses and makes it more difficult to complete repairs to the structure.


To repair this structure, we would recommend that all the cross beams and floor beams be replaced, concrete repairs be completed, the trusses be straightened out as much as reasonably possible, the deck boards be replaced, and miscellaneous other tasks be completed to address all deficiencies identified. When including a contingency, approvals and engineering in the estimate, we calculated that the total probable costs, excluding HST, will be approximately \$400,000. The last set of repairs to the bridge took place 16 years earlier; however, given that the abutment has shifted in the past, we are unsure how long this rehabilitated structure will last before it is necessary to decide whether to repair or replacement the structure again.


We have also calculated a probable cost to replace the bridge. When replacing the bridge, it is assumed the structure would be reconstructed as a two-lane concrete structure up to current codes requirements, with reconstructed approaches so the alignment of the bridge is improved to better line up with the road. The total probable cost to construct a replacement structure, including Engineering, approvals, etc. was calculated to be about \$3,070,000, excluding HST.

If you have any questions about this report or our recommendations, feel free to contact us.

Yours very truly

B. M. ROSS AND ASSOCIATES LIMITED

Per   
Ken Logtenberg, P. Eng.


Per   
Colin Van Niejenhuis, P. Eng.

KDL:hv  
Encl.

**Summary Report:**



2-West Elevation



Datum: NAD83 17N    Northing: 4906509    Easting: 481708

<b>Structure Name:</b> <span style="border: 1px solid black; padding: 2px;">Pearces Bridge</span>	<b>BMROSS File #:</b> <span style="border: 1px solid black; padding: 2px;">BR-280</span>	<b>MTO #:</b> <span style="border: 1px solid black; padding: 2px;"></span>
<b>Main Hwy / Road #:</b> <span style="border: 1px solid black; padding: 2px;"></span>	<b>Bridge Condition Index (BCI):</b> <span style="border: 1px solid black; padding: 2px;">40</span>	<b>CRV:</b> <span style="border: 1px solid black; padding: 2px;">\$1,619,900</span>
<b>Road Name:</b> <span style="border: 1px solid black; padding: 2px;">Sideroad 5</span>	<b>Inspection Date:</b> <span style="border: 1px solid black; padding: 2px;">5/31/2024</span>	
<b>Structure Location:</b> <span style="border: 1px solid black; padding: 2px;">Concession 6</span>	<b>Next Inspection:</b> <span style="border: 1px solid black; padding: 2px;">1/1/2026</span>	
<b>Condition Summary:</b> <span style="border: 1px solid black; padding: 2px;">Replacement recommended</span>	<b>Recommended Timing:</b> <span style="border: 1px solid black; padding: 2px;">Within 1 yr.</span>	<b>Current Load Limit:</b> <span style="border: 1px solid black; padding: 2px;">8</span>
<b>Overall Comments:</b> Half through truss in poor condition. In lieu of completing extensive repairs; recommend closure and replacement of structure.		

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
	Replace structure	Within 1 yr.	\$2,100,000
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$973,000
		<b>Total</b>	<b>\$3,073,000</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <span style="border: 1px solid black; padding: 2px;">Pearces Bridge</span>		Crossing Type: <span style="border: 1px solid black; padding: 2px;">Navigable Waterway</span>	
Main Hwy / Road #: <span style="border: 1px solid black; padding: 2px;"></span>	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>		
Road Name: <span style="border: 1px solid black; padding: 2px;">Sideroad 5</span>	Northing: <span style="border: 1px solid black; padding: 2px;">4906509</span>		
Structure Location: <span style="border: 1px solid black; padding: 2px;">Concession 6</span>	Easting: <span style="border: 1px solid black; padding: 2px;">481708</span>		
Owner(s): <span style="border: 1px solid black; padding: 2px;">Municipality of Arran-Elderslie</span>	Heritage Designation: <span style="border: 1px solid black; padding: 2px;">Not Designated</span>		
MTO Region: <span style="border: 1px solid black; padding: 2px;">Southwestern</span>	Road Class: <span style="border: 1px solid black; padding: 2px;">Local</span>		
MTO District: <span style="border: 1px solid black; padding: 2px;">Owen Sound</span>	Posted Speed: <span style="border: 1px solid black; padding: 2px;"></span>	No. of Lanes: <span style="border: 1px solid black; padding: 2px;">2</span>	
Current County: <span style="border: 1px solid black; padding: 2px;">Bruce</span>	AADT: <span style="border: 1px solid black; padding: 2px;">200-499</span>	% Trucks: <span style="border: 1px solid black; padding: 2px;"></span>	
Geographic Twp.: <span style="border: 1px solid black; padding: 2px;">ELDERSLIE</span>	Special Routes: <span style="border: 1px solid black; padding: 2px;"></span>		
Structure Group: <span style="border: 1px solid black; padding: 2px;">Truss</span>	Surface Type: <span style="border: 1px solid black; padding: 2px;">Wood</span>		
Structure Type: <span style="border: 1px solid black; padding: 2px;">Half-Through Truss</span>	Detour Length Around Bridge: <span style="border: 1px solid black; padding: 2px;"></span> (km)		
Total Deck Length: <span style="border: 1px solid black; padding: 2px;">29.3</span> (m)	Fill on Structure: <span style="border: 1px solid black; padding: 2px;">0</span> (m)		
Overall Str. Width: <span style="border: 1px solid black; padding: 2px;">5.7</span> (m)	Skew Angle: <span style="border: 1px solid black; padding: 2px;">0</span> (Degrees)		
Total Struct. Area: <span style="border: 1px solid black; padding: 2px;">167.01</span> (sq.m)	Direction of Structure: <span style="border: 1px solid black; padding: 2px;">North/South</span>		
Roadway Width: <span style="border: 1px solid black; padding: 2px;">4.8</span> (m)	Min. Vert. Clearance: <span style="border: 1px solid black; padding: 2px;"></span> (m)		
Number of Spans: <span style="border: 1px solid black; padding: 2px;">1</span>	Bridge Condition Index: <span style="border: 1px solid black; padding: 2px;">40</span>		
Span Length(s): <span style="border: 1px solid black; padding: 2px;">27.1</span> (m) <span style="border: 1px solid black; padding: 2px;"></span> (m) <span style="border: 1px solid black; padding: 2px;"></span> (m) <span style="border: 1px solid black; padding: 2px;"></span> (m) <span style="border: 1px solid black; padding: 2px;"></span> (m)			
MTO Number: <span style="border: 1px solid black; padding: 2px;"></span>	BMROSS File Number: <span style="border: 1px solid black; padding: 2px;">BR-280</span>		

**Historical Data:**

Year Built: <span style="border: 1px solid black; padding: 2px;">1930</span>	Last Biennial Inspection: <span style="border: 1px solid black; padding: 2px;">2022</span>
Current Load Limit: <span style="border: 1px solid black; padding: 2px;">8</span> (tonnes)	Last Evaluation: <span style="border: 1px solid black; padding: 2px;"></span>
Load Limit By-Law #: <span style="border: 1px solid black; padding: 2px;"></span>	Last Enhanced Inspection: <span style="border: 1px solid black; padding: 2px;"></span>
By-Law Expiry Date: <span style="border: 1px solid black; padding: 2px;"></span>	Enhanced Access Equipment: <span style="border: 1px solid black; padding: 2px;"></span>

**Rehabilitation / Investigation History:**

Year	Work Type	Description	Cost
2008		Deck replaced and stringers replaced	0
2002		Some stringers replaced	0
1971		South abutment repaired	0

Field Inspection Information:		
Date of Inspection: 5/31/2024	Inspection Type: OSIM Inspector	Next Detailed Inspection: 2026
Inspector: Ken Logtenberg		
Inspecting Firm: BM Ross & Associates Limited		
Others in Party: Andrew McGarvey		
Equipment Used: Hammer, Camera, Measuring Tape, Chain		
Weather: Sunny, Slight Breeze		
Temperature: 15 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Replacement recommended	<b>Recommended Timing:</b> Within 1 yr.
<b>Overall Comments:</b> Half through truss in poor condition. In lieu of completing extensive repairs; recommend closure and replacement of structure.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">167</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">1,619,900</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">9,700.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
	Replace structure	Within 1 yr.	\$2,100,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$2,100,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$60,000
Approaches	Removal and re-align approaches when constructing new abutments	\$320,000
Traffic Control / Detours		\$10,000
Utilities		\$0
Right of Way		\$0
Environmental Study		\$23,000
Engineering		\$260,000
Other	Bonding and Insurance	\$50,000
Contingencies		\$250,000
<b>Associated Work Sub-Total:</b>		<b>\$973,000</b>
<b>Total Cost:</b>		<b>\$3,073,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	8.2	
Location:				Height:	2.3	
Material:	Cast-in-place Concrete			Count:	2	
Element Type:	Gravity Wall			Total Quantity:	37.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			90% (33.93)	10% (3.77)	\$33,930	\$12,215
Comments:	Abutments moved forward sometime in the past. South abutment has large crack and some efflorescence staining through smaller cracks. Cannot be sure abutment will not shift forward further in future.					
Performance Deficiencies:	None					
Recommended Work:	In lieu of concrete repairs recommend replace the structure.				Recommended Timing:	< 1 year
					Maintenance Priority:	
Maintenance needs:						
Maintenance work:						
Element Data:						
Element Group:	Abutments			Length:	4.6	
Element Name:	Wingwalls			Width:		
Location:				Height:	3.0	
Material:	Cast-in-place Concrete			Count:	4	
Element Type:	Reinforced Concrete			Total Quantity:	27.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (27.6)		\$9,660	\$3,864
Comments:	Wingwalls attached to abutment and at least one abutment shifted forward.					
Performance Deficiencies:	None					
Recommended Work:	Replace structure.				Recommended Timing:	< 1 year
					Maintenance Priority:	
Maintenance needs:						
Maintenance work:						
Element Data:						
Element Group:	Barriers			Length:	29.3	
Element Name:	Railing Systems			Width:	0.05	
Location:				Height:	1.1	
Material:	Steel			Count:	2	
Element Type:	Steel Flex Beam on Steel Post			Total Quantity:	117.2 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	Galvanized			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (117.2)			\$23,440	\$17,580
Comments:	Appears sound.					
Performance Deficiencies:	None					
Recommended Work:	Replace structure.				Recommended Timing:	< 1 year
					Maintenance Priority:	
Maintenance needs:						
Maintenance work:						

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: E12


Element Data:						
Element Group:	Beams/MLE's			Length:		
Element Name:	Diaphragms			Width:		
Location:				Height:		
Material:	Steel			Count:	6	
Element Type:	Cross Type			Total Quantity:	6 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			50% (3)	50% (3)	\$0	\$0
Comments:	Top flange of some cross beams appear to have lost 50% of top flange, rusted away. Southernmost and second from north appear to be in poorest condition.					
Performance Deficiencies:						
Recommended Work:	In lieu of replacing all cross beams, replace structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	4.0	
Element Name:	Floor Beams			Width:	0.09	
Location:				Height:	0.18	
Material:	Steel			Count:	49	
Element Type:	I-type			Total Quantity:	123.5 m2	
Environment:	Moderate			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			70% (86.45)	30% (37.05)	\$51,870	\$14,524
Comments:	Many floor beams are rusted through and providing no support for deck. From north to south: Bay 1 - 1 poor, 6 fair. Bay 2 - 4 poor, 3 fair. Bay 3 - 2 poor, 5 fair. Bay 4 - 2 poor, 5 fair. Bay 5 - 1 poor, 6 fair. Bay 6 - 3 poor, 4 fair. Bay 7 - fair.					
Performance Deficiencies:						
Recommended Work:	In lieu of replacing all the floor beams, replace the structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Bracing			Length:		
Element Name:	Bracing			Width:		
Location:				Height:		
Material:	Steel			Count:	16	
Element Type:				Total Quantity:	16 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			90% (14.4)	10% (1.6)	\$8,000	\$2,880
Comments:	Diagonal cross bracing. Only found one in poor condition but are old like other members and slowly deteriorating.					
Performance Deficiencies:						
Recommended Work:	Replace structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



# Ontario Structure Inspection Manual - Inspection Report:

Site Number: E12

Element Data:						
Element Group:	Decks			Length:	29.3	
Element Name:	Deck Top - Thin Slab			Width:	4.9	
Location:				Height:	0.14	
Material:	Wood			Count:	1	
Element Type:	Laminated Wood Decking - transverse			Total Quantity:	143.6 m2	
Environment:	Severe			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	Other			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (143.6)		\$17,232	\$6,893
Comments:	Abrasion to wood wearing down the surface of deck. Wooden deck allows water through and onto the floor beams below that are corroding. Deck would have to be removed to complete other repairs.					
Performance Deficiencies:	None					
Recommended Work:	Replace structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	27.1	
Element Name:	Bottom Chords			Width:	0.16	
Location:				Height:	0.08	
Material:	Steel			Count:	2	
Element Type:				Total Quantity:	2 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (2)	\$600	\$0
Comments:	At north end, both bottom chords buckled by abutment moving inwards. Monitor. Gravel on bottom chords and bearing seats.					
Performance Deficiencies:	None					
Recommended Work:	In lieu of repairs recommend replacing the structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:	Remove gravel from bottom chords and bearing seats			Maintenance Priority:	Within 1 Yr.	
Element Data:						
Element Group:	Trusses/Arches			Length:		
Element Name:	Top Chords			Width:		
Location:				Height:		
Material:	Steel			Count:		
Element Type:	T-type			Total Quantity:		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			80% ()	20% ()		\$0
Comments:	Element includes remaining truss members (top chord, vertical and diagonal members). Curve in top chord of each truss. Coating system is not protecting steel and surface rust is present throughout trusses.					
Performance Deficiencies:						
Recommended Work:	Replace structure.				Recommended Timing:	< 1 year
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing North



2-West Elevation





3-Soffit Looking North



4-South Abutment and South Stringer





May 31, 2024 10:12 a.m.


5-Bay 2 Stringers



May 31, 2024 10:21 a.m.

6-Bay 2 Crossbeam






7-Bent West Bottom Chord




8-Crossbeam and Corroded Stringer



May 31, 2024 10:05 a.m.

9-Deck Top



May 31, 2024 11:02 a.m.

Bent East Bottom Chord





Crossbeam



Top Chord-East Truss

