


## Summary Report:



Looking North



Datum: NAD83 17N Northing: 4906405 Easting: 478200

Structure Name: Ross St. Bridge

BMROSS File #:

MTO #:

Main Hwy / Road #:

Bridge Condition Index (BCI):

69

CRV: \$872,200

Road Name: Ross Street

Inspection Date: 2020-09-18

Structure Location:

Next Inspection: 2022-01-01

Condition Summary: Repairs recommended

Recommended Timing: 1-5 Years

Current Load Limit: N/A

Overall Comments: Box beam of girders in fair condition. Recommend patch repairing abutment walls, barriers and deck. Waterproof and pave deck.

## Repair / Rehabilitation:

Element:	Work Required	Period	Cost
Abutments	Patch repair abutment walls	1 to 5 yrs.	\$1,500
Decks	Patch repair	1 to 5 yrs.	\$27,500
Decks	Waterproof and pave	1 to 5 yrs.	\$28,000
Sidewalks/curbs	Patch repair	1 to 5 yrs.	\$1,000
			\$0
			\$0
			\$0
Various	Associated Work		\$44,500
		<b>Total</b>	<b>\$102,500</b>

## Additional Investigations:

## Maintenance Needs: